




## HF-1 TLT Axial Fan Parts Aluminum Impeller Fan Blades S1GA0193

Our Product Introduction

### Basic Information

- Place of Origin: Shanghai
- Brand Name: YIKU
- Model Number: S1GA0193
- Minimum Order Quantity: 1 piece
- Price: negotiable
- Packaging Details: Wooden box
- Delivery Time: 2-3month
- Payment Terms: L/C, T/T
- Supply Ability: 20 units/month



### Product Specification

- Name: Aluminum Blade
- Model: S1GA0193
- Material: HF-1
- Weight: 15.4kg
- Purpose: Combustion Support, Coal Powder Delivery
- Applicable To: Forced Draft Fan, Primary Air Fan
- Highlight: **aluminum TLT Axial Fan Parts,  
aluminum impeller fan blades,  
Axial Fan Parts impeller fan blades**


for more products please visit us on [axialfanparts.com](http://axialfanparts.com)

## Product Description

HF-1 aluminum blade fan impeller blade

配叶片、叶柄孔和叶柄的序号

Assembly blade, handle hole and handle serial No



在力,水泥,造等行中大量使用的机,因送的气体介中含有大量的硬粉粒和酸性气体,些的流部件,受到烈的冲刷腐,尤其是其心部件叶,在其叶片的末端行速度到160米秒,磨速度比其它部位更重.尤其是机叶片的磨最重,因而使机子的平衡遭到破坏,引起机振,短机寿命,重可使机不能正常工作.

Fan equipment widely used in the electric power, steel, cement, paper and other industries, because the gas medium contains a large number of hard dust particles and acidic gases, the flow parts of these equipment are strongly eroded and corroded, especially the heart part of the impeller, the running line speed at the end of the blade reaches 160 meters per second, and the wear rate is more serious than other parts. In particular, the wear of the fan blade is the most serious, so that the balance of the fan rotor is destroyed, causing fan vibration, shortening the life of the fan, and in serious cases, the fan can not work normally.



Shanghai YIKU Power Equipment Co., Ltd



8613916002258



657925203@qq.com



[axialfanparts.com](http://axialfanparts.com)

5587 Dongchuan Road, Pudong New Area, Shanghai